

L Number	Hits	Search Text	DB	Time stamp
1	0	(moisture adj2 sensor) and inundation	USPAT; EPO; JPO; DERWENT	2004/06/08 14:12
2	643	(moisture adj2 sensor) and \$closure	USPAT; EPO; JPO; DERWENT	2004/06/08 14:12
3	7	((moisture adj2 sensor) and \$closure) and (optical adj2 cable)	USPAT; EPO; JPO; DERWENT	2004/06/08 14:13
4	0	5903221.URPN.	USPAT	2004/06/08 14:14
5	11	("4480251" "4754264" "4866265" "5077526" "5262639" "5274359" "5349182" "5469146" "5614893" "5708364" "5731990").PN.	USPAT	2004/06/08 14:14
-	1	((optical adj2 cable) and closure and sensor and (temperature humidity)) and inundation	USPAT; EPO; JPO; DERWENT	2004/06/08 14:11
-	0	99073136.URPN.	USPAT	2003/07/25 15:20
-	42	(optical adj2 cable) and closure and sensor and (temperature humidity)	USPAT; EPO; JPO; DERWENT	2003/07/25 15:21
-	13	5430815.URPN.	USPAT	2003/07/25 15:23
-	785	(optical adj2 cable) and closure	USPAT; EPO; JPO; DERWENT	2003/07/25 15:44
-	3	((optical adj2 cable) and closure) and sensor and (temperature and humidity)	USPAT; EPO; JPO; DERWENT	2003/07/25 15:45
-	1	((water adj2 (sensor sensing) adj2 meter)) and optical	USPAT; EPO; JPO; DERWENT	2003/07/25 15:46
-	11	(water adj2 (sensor sensing) adj2 meter)	USPAT; EPO; JPO; DERWENT	2003/07/25 15:47
-	149	(water adj2 sensor) and meter and optical	USPAT; EPO; JPO; DERWENT	2003/07/25 15:47
-	25	((water adj2 sensor) and meter and optical) and (temperature and humidity)	USPAT; EPO; JPO; DERWENT	2003/07/25 15:49
-	38	enclosure and (optical adj2 cable) and sensor and alarm	USPAT; EPO; JPO; DERWENT	2003/07/25 15:54

-	156	("3327584" "3436157" "3507042" "3555262" "3743429" "3748741" "3778541" "3940608" "3986777" "4054389" "4115922" "4125329" "4184175" "4207678" "4241738" "4278353" "4290433" "4324546" "4382784" "4411626" "4434654" "4464054" "4487206" "4505589" "4560275" "4568191" "4575805" "4616933" "4654794" "4666309" "4687329" "4707138" "4728290" "4730922" "4773063" "4798951" "4823169" "4836674" "4844617" "4878485" "4881811" "4914512" "4917500" "4957371" "4966458" "4986671" "4988206" "5017772" "5028139" "5040940" "5095210" "5139335" "5142383" "5159199" "5164597" "5166755" "5193525" "5229841" "5245404" "5306144" "5308771" "5309256" "5329935" "5369481" "5371586" "5377669" "5383020" "5386292" "5392110" "5401954" "5401967" "5404218" "5410410" "5410413" "5428450" "5450193" "5450203" "5450511" "5453838" "5457525" "5461476" "5467289" "5469249" "5474449" "5477332" "5479252" "5483335" "5487661" "5497227" "5498157" "5533628" "5560355" "5565976" "5575284" "5583631" "5590251" "5592294" "5604594" "5609978" "5625459" "5668633" "5671735" "5683243" "5690486" "5695949" "5696751" "5742060" "5745229" "5754283" "5757496" "5759030" "5766006" "5774610" "5784507" "5798839" "5822474" "5850195" "5850301" "5851113" "5871351" "5880826" "5883708" "5924981" "5926262" "5961324" "5961327" "5966205" "5989022" "5995235" "6002488" "6007332" "6008905" "6030209" "6031928" "6038016" "6038024" "6040902" "6052195" "6057925" "6086274" "6118521" "6127673" "6188471" "6222620" "6233047" "6239868" "6246471" "6246479" "6249339" "6249340" "6249348" "6254385" "6264470" "6271913" "6301004" "6307629").PN.	USPAT	2003/07/25 15:51
-	205	enclosure and ((temperature and humidity) adj2 sensor)	USPAT; EPO; JPO; DERWENT	2003/07/25 15:55
-	3	(enclosure and ((temperature and humidity) adj2 sensor)) and (optical adj2 cable)	USPAT; EPO; JPO; DERWENT	2003/07/25 16:04
-	0	(water same tank) and (humitdity and temperature) and sensor	USPAT; EPO; JPO; DERWENT	2003/07/25 16:04
-	848	(water adj2 meter) and (enclosure tank)	USPAT; EPO; JPO; DERWENT	2003/07/25 16:05
-	0	((water adj2 meter) and (enclosure tank)) and humitity and temperature	USPAT; EPO; JPO; DERWENT	2003/07/25 16:05
-	30	((water adj2 meter) and (enclosure tank)) and humidity and temperature	USPAT; EPO; JPO; DERWENT	2003/07/25 16:12
-	302	enclosure and (humidity adj2 sensor) and temperature	USPAT; EPO; JPO; DERWENT	2003/07/25 16:13
-	205	(enclosure and (humidity adj2 sensor) and temperature) and (temperature adj2 sensor)	USPAT; EPO; JPO; DERWENT	2003/07/25 16:13
-	57	((enclosure and (humidity adj2 sensor) and temperature) and (temperature adj2 sensor)) and optical	USPAT; EPO; JPO; DERWENT	2003/07/25 16:13
-	32	((enclosure and (humidity adj2 sensor) and temperature) and (temperature adj2 sensor)) and optical) and inside	USPAT; EPO; JPO; DERWENT	2003/07/25 17:34

-	355	(enclosure box container) and (temperature adj2 sensor) and inside and (humidity adj2 sensor)	USPAT; EPO; JPO; DERWENT	2003/07/25 17:35
-	103	((enclosure box container) and (temperature adj2 sensor) and inside and (humidity adj2 sensor)) and optical	USPAT; EPO; JPO; DERWENT	2003/07/25 17:35
-	5	((enclosure box container) and (temperature adj2 sensor) and inside and (humidity adj2 sensor)) and ((optical optic) adj2 cable)	USPAT; EPO; JPO; DERWENT	2003/07/25 17:37
-	31	((enclosure box container) and (temperature adj2 sensor) and inside and (humidity adj2 sensor)) and optical) and alarm	USPAT; EPO; JPO; DERWENT	2003/07/25 17:37
-	16518	sealed same enclosure	USPAT; EPO; JPO; DERWENT	2003/07/28 10:00
-	155	(sealed same enclosure) and (optical adj2 sensor)	USPAT; EPO; JPO; DERWENT	2003/07/28 10:00
-	4	((sealed same enclosure) and (optical adj2 sensor)) and (optical adj2 cable)	USPAT; EPO; JPO; DERWENT	2003/07/28 10:22
-	44	4545253.URPN.	USPAT	2003/07/28 10:03
-	34	("4509370" "4545253" "4577100" "4589285" "4649529" "4859844" "4900937" "4932262" "4932263" "4996419" "5012090" "5042898" "5144690" "5163321" "5308973" "5315110" "5351324" "5357806" "5363463" "5399854" "5401956" "5414507" "5444803" "5452087" "5485745" "5495237" "5499533" "5548116" "5633748" "5646401" "5680489" "5684297" "5767411" "5808779").PN.	USPAT	2003/07/28 10:04
-	18	(fiber adj3 optic\$ adj3 cable) and (water adj2 sensor) and (temperature humidity)	USPAT; EPO; JPO; DERWENT	2003/07/28 13:32
-	54	container and (inside same (humidity and temperature)) and sensor and optical	USPAT; EPO; JPO; DERWENT	2003/07/28 13:34
-	40	(container and (inside same (humidity and temperature)) and sensor and optical) and water	USPAT; EPO; JPO; DERWENT	2003/07/28 13:42
-	411	inundation	USPAT; EPO; JPO; DERWENT	2003/07/28 13:42
-	2	inundation and optical and (enclosure closure box container) and (sensor monitor detector) and temperature	USPAT; EPO; JPO; DERWENT	2003/07/28 13:47
-	0	manhole and (atmosphere environment) and water and (optical adj3 cable) and maintenance and monitoring	USPAT; EPO; JPO; DERWENT	2003/07/28 13:48
-	3	(optical same closure same maintenance same cable same water)	USPAT; EPO; JPO; DERWENT	2003/07/28 13:51
-	0	99073136.URPN.	USPAT	2003/07/28 13:50
-	2169098	(KR 99073136A KR 280379B KR 280379B WO 200073834A1)	USPAT; EPO; JPO; DERWENT	2003/07/28 13:52
-	2408	((KR 99073136A KR 280379B KR 280379B WO 200073834A1)) and (optical adj2 cable)	USPAT; EPO; JPO; DERWENT	2003/07/28 13:53
-	311	((KR 99073136A KR 280379B KR 280379B WO 200073834A1)) and (optical adj2 cable)) and (enclosure closure container box)	USPAT; EPO; JPO; DERWENT	2003/07/28 13:53
-	16	((KR 99073136A KR 280379B KR 280379B WO 200073834A1)) and (optical adj2 cable)) and (enclosure closure container box)) and water and temperature and humidity	USPAT; EPO; JPO; DERWENT	2003/07/28 13:53

-	190	("5774618" "5450518" "5652820" "5479554" "5793921" "5793920" "5825961" "5970199" "6314229" "6321017" "6385381" "5396575" "4516830" "5185844" "5481639" "5530782" "5790741" "4266853" "4498732" "4799757" "4805979" "4866265" "5185845" "5280556" "5420957" "5625737" "5689598" "5760364" "5778122" "5787219" "5835657" "5993931" "6009225" "6021246" "6178283" "6192180" "6246821" RE31579 "4460419" "4779950" "4790648" "4815813" "4820007" "4849723" "4874904" "4879436" "4881792" "4927227" "4932744" "4958903").pn. ("4964689" "4986761" "4991928" "5007703" "5011416" "5016952" "5069516" "5043037" "5042901" "5185843" "5189723" "5189725" "5210812" "5217808" "5249248" "5261024" "5269206"	USPAT; EPO; JPO; DERWENT	2003/07/30 14:27
Search History	6/8/04 2:17:21 PM Page 4			
C:\APPS\EAStworkspaces\enclosure with optical water sensor.wsp				

-	75	("5774618" "5450518" "5652820" "5479554" "5793921" "5793920" "5825961" "5970199" "6314229" "6321017" "6385381" "5396575" "4516830" "5185844" "5481639" "5530782" "5790741" "4266853" "4498732" "4799757" "4805979" "4866265" "5185845" "5280556" "5420957" "5625737" "5689598" "5760364" "5778122" "5787219" "5835657" "5993931" "6009225" "6021246" "6178283" "6192180" "6246821" RE31579 "4460419" "4779950" "4790648" "4815813" "4820007" "4849723" "4874904" "4879436" "4881792" "4927227" "4932744" "4958903").pn. ("4964689" "4986761" "4991928" "5007703" "5011416" "5016952" "5069516" "5043037" "5042901" "5185843" "5189723" "5189725" "5210812" "5217808" "5249248" "5261024" "5269206"	USPAT; EPO; JPO; DERWENT	2003/07/30 14:27
Search History	6/8/04 2:17:21 PM Page 5			
C:\APPS\EAST\workspaces\enclosure with optical water sensor.wsp				

	14	(((("5774618" "5450518" "5652820" "5479554" "5793921" "5793920" "5825961" "5970199" "6314229" "6321017" "6385381" "5396575" "4516830" "5185844" "5481639" "5530782" "5790741" "4266853" "4498732" "4799757" "4805979" "4866265" "5185845" "5280556" "5420957" "5625737" "5689598" "5760364" "5778122" "5787219" "5835657" "5993931" "6009225" "6021246" "6178283" "6192180" "6246821" RE31579 "4460419" "4779950" "4790648" "4815813" "4820007" "4849723" "4874904" "4879436" "4881792" "4927227" "4932744" "4958903").pn. ("4964689" "4986761" "4991928" "5007703" "5011416" "5016952" "5069516" "5043037" "5042901" "5185843" "5189723" "5189725" "5210812" "5217808" "5249248" "5261024" "5269206"	USPAT; EPO; JPO; DERWENT	2003/07/30 14:29
Search History	6/8/04 2:17:21 PM Page 6			
C:\APPS\EAST\workspaces\enclosure with optical water sensor.wsp				

-	26	("5774618" "5450518" "5652820" "5479554" "5793921" "5793920" "5825961" "5970199" "6314229" "6321017" "6385381" "5396575" "4516830" "5185844" "5481639" "5530782" "5790741" "4266853" "4498732" "4799757" "4805979" "4866265" "5185845" "5280556" "5420957" "5625737" "5689598" "5760364" "5778122" "5787219" "5835657" "5993931" "6009225" "6021246" "6178283" "6192180" "6246821" RE31579 "4460419" "4779950" "4790648" "4815813" "4820007" "4849723" "4874904" "4879436" "4881792" "4927227" "4932744" "4958903").pn. ("4964689" "4986761" "4991928" "5007703" "5011416" "5016952" "5069516" "5043037" "5042901" "5185843" "5189723" "5189725" "5210812" "5217808" "5249248" "5261024" "5269206"	USPAT; EPO; JPO; DERWENT	2003/07/30 14:29
Search History	6/8/04 2:17:21 PM, Page 7			
C:\APPS\EAST\workspaces\enclosure with optical water sensor.wsp				

-	26	(((("5774618" "5450518" "5652820" "5479554" "5793921" "5793920" "5825961" "5970199" "6314229" "6321017" "6385381" "5396575" "4516830" "5185844" "5481639" "5530782" "5790741" "4266853" "4498732" "4799757" "4805979" "4866265" "5185845" "5280556" "5420957" "5625737" "5689598" "5760364" "5778122" "5787219" "5835657" "5993931" "6009225" "6021246" "6178283" "6192180" "6246821" RE31579 "4460419" "4779950" "4790648" "4815813" "4820007" "4849723" "4874904" "4879436" "4881792" "4927227" "4932744" "4958903").pn. ("4964689" "4986761" "4991928" "5007703" "5011416" "5016952" "5069516" "5043037" "5042901" "5185843" "5189723" "5189725" "5210812" "5217808" "5249248" "5261024" "5269206"	USPAT; EPO; JPO; DERWENT	2003/07/30 14:31
Search History	6/8/04 2:17:21 PM Page 8			
C:\APPS\EAST\workspaces\enclosure with optical water sensor.wsp				

-	128	("5774618" "5450518" "5652820" "5479554" "5793921" "5793920" "5825961" "5970199" "6314229" "6321017" "6385381" "5396575" "4516830" "5185844" "5481639" "5530782" "5790741" "4266853" "4498732" "4799757" "4805979" "4866265" "5185845" "5280556" "5420957" "5625737" "5689598" "5760364" "5778122" "5787219" "5835657" "5993931" "6009225" "6021246" "6178283" "6192180" "6246821" RE31579 "4460419" "4779950" "4790648" "4815813" "4820007" "4849723" "4874904" "4879436" "4881792" "4927227" "4932744" "4958903").pn. ("4964689" "4986761" "4991928" "5007703" "5011416" "5016952" "5069516" "5043037" "5042901" "5185843" "5189723" "5189725" "5210812" "5217808" "5249248" "5261024" "5269206"	USPAT; EPO; JPO; DERWENT	2003/07/30 14:31
Search History	6/8/04 2:17:21 PM Page 9			
C:\APPS\EAST\workspaces\enclosure with optical water sensor.wsp				

	0	(((("5774618" "5450518" "5652820" "5479554" "5793921" "5793920" "5825961" "5970199" "6314229" "6321017" "6385381" "5396575" "4516830" "5185844" "5481639" "5530782" "5790741" "4266853" "4498732" "4799757" "4805979" "4866265" "5185845" "5280556" "5420957" "5625737" "5689598" "5760364" "5778122" "5787219" "5835657" "5993931" "6009225" "6021246" "6178283" "6192180" "6246821" RE31579 "4460419" "4779950" "4790648" "4815813" "4820007" "4849723" "4874904" "4879436" "4881792" "4927227" "4932744" "4958903").pn. ("4964689" "4986761" "4991928" "5007703" "5011416" "5016952" "5069516" "5043037" "5042901" "5185843" "5189723" "5189725" "5210812" "5217808" "5249248" "5261024" "5269206"	USPAT; EPO; JPO; DERWENT	2003/07/30 14:31
Search History	6/8/04 2:17:21 PM	Page 10		
C:\APPS\EAST\workspaces\enclosure with optical water sensor.wsp				

-	6	(((("5774618" "5450518" "5652820" "5479554" "5793921" "5793920" "5825961" "5970199" "6314229" "6321017" "6385381" "5396575" "4516830" "5185844" "5481639" "5530782" "5790741" "4266853" "4498732" "4799757" "4805979" "4866265" "5185845" "5280556" "5420957" "5625737" "5689598" "5760364" "5778122" "5787219" "5835657" "5993931" "6009225" "6021246" "6178283" "6192180" "6246821" RE31579 "4460419" "4779950" "4790648" "4815813" "4820007" "4849723" "4874904" "4879436" "4881792" "4927227" "4932744" "4958903").pn. ("4964689" "4986761" "4991928" "5007703" "5011416" "5016952" "5069516" "5043037" "5042901" "5185843" "5189723" "5189725" "5210812" "5217808" "5249248" "5261024" "5269206"	USPAT; EPO; JPO; DERWENT	2003/07/30 15:05
Search History	6/8/04 2:17:21 PM	Page 11		
C:\APPS\EAST\workspaces\enclosure with optical water sensor.wsp				

-	2	("5647045" "5781686").PN.	USPAT	2003/07/30 14:32
-	319	359/512	USPAT; EPO; JPO; DERWENT	2003/07/30 15:05
-	3	359/512 and closure	USPAT; EPO; JPO; DERWENT	2003/07/30 15:05
-	47	359/512 and (enclosure closure box container)	USPAT; EPO; JPO; DERWENT	2003/07/30 15:06
-	0	(359/512 and (enclosure closure box container)) and (optical adj2 cable)	USPAT; EPO; JPO; DERWENT	2003/07/30 15:06
-	0	359/512 and (optical adj2 cable)	USPAT; EPO; JPO; DERWENT	2003/07/30 15:06
-	760	435/808	USPAT; EPO; JPO; DERWENT	2003/07/30 15:07
-	3	435/808 and (optical adj2 cable)	USPAT; EPO; JPO; DERWENT	2003/07/30 15:08
-	494	(optical adj2 cable) and (internal inside) and (container closure enclosure box) and (monitoring sensing detecting)	USPAT; EPO; JPO; DERWENT	2003/07/30 15:09
-	236	((optical adj2 cable) and (internal inside) and (container closure enclosure box) and (monitoring sensing detecting)) and (temperature humidity)	USPAT; EPO; JPO; DERWENT	2003/07/30 15:09
-	0	((((optical adj2 cable) and (internal inside) and (container closure enclosure box) and (monitoring sensing detecting)) and (temperature humidity)) and maintenance) and manhole	USPAT; EPO; JPO; DERWENT	2003/07/30 15:10
-	52	((((optical adj2 cable) and (internal inside) and (container closure enclosure box) and (monitoring sensing detecting)) and (temperature humidity)) and maintenance	USPAT; EPO; JPO; DERWENT	2003/07/30 15:10